

ACS CARS

Übersicht Fahrzeugabdeckung zur Kalibrierung der Rückfahrkamera

(Stand 18.11.2019; Softwareversion 5.28.00)

Nachfolgend finden Sie eine Übersicht über alle Rückfahrkamera-Systeme, welche sich mithilfe unseres Kalibriersystems **ACS cars** kalibrieren lassen.

ACS cars von WOW! Würth Online World bietet Ihnen ein flexibles und kostengünstiges System für die Kalibrierung statischer und dynamischer Kamera- und Radarsysteme. Bestehend aus Hardware- und Softwarelösungen stellt das Kalibriersystem die optimale Lösung für den fordernden Werkstattalltag dar.

Marke	Modell	Baujahre	Kamerasystem	Verfügbar ab WOW! Softwareversion	Systemtyp	Spezialwerkzeug notwendig?	Kalibrierart	Hinweis wann Kalibrierung notwendig wird
KIA	Niro [17-]	2017-2019	PGS (Parking guide system)	5.00.26	Rear View Camera	NEIN	Statisch	a; b; c; d; e; f
Mercedes	A-Class [W177]	2018-2019	PARKMAN213 (Parking assistance)	5.00.23	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	AMG GT [W190]	2019-2019	PARKMAN213 (Parking assistance)	5.28.00	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	AMG GT 4-Door Coupé [X290]	2019-2019	PARKMAN213 (Parking assistance)	5.00.26	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	B-Class [W247]	2019-2019	PARKMAN213 (Parking assistance)	5.00.26	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	C-Class [W205] [2019-]	2019-2019	PARKMAN213 (Parking assistance)	5.00.26	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	CLA-Class [C118]	2019-2019	PARKMAN213 (Parking assistance)	5.00.26	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	CLS [C257]	2018-2019	PARKMAN213 (Parking assistance)	5.00.22	Rear View Camera	NEIN	Dynamisch	a; b; c; d

Mercedes	E-Class [W213]	2016-2019	PARKMAN213 (Parking assistance)	5.00.17	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	E-Class Coupé [C238]	2017-2019	PARKMAN213 (Parking assistance)	5.00.22	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	G-Class [W463] [2019-]	2019-2019	PARKMAN213 (Parking assistance)	5.00.26	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	GLB-Class [X247]	2019-2020	PARKMAN213 (Parking assistance)	5.28.00	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	GLC-Class [X253] [2020-]	2020-2020	PARKMAN213 (Parking assistance)	5.28.00	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	GLE [W167]	2019-2019	PARKMAN213 (Parking assistance)	5.00.26	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	GLS [X167]	2019-2020	PARKMAN213 (Parking assistance)	5.28.00	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	S-Class [W222]	2018-2019	PARKMAN213 (Parking assistance)	5.00.22	Rear View Camera	NEIN	Dynamisch	a; b; c; d
Mercedes	S-Class Coupé [C217] [2018-]	2018-2019	PARKMAN213 (Parking assistance)	5.27.00	Rear View Camera	NEIN	Dynamisch	a; b; c; d

Legende:

- a - Fehlercode vorhanden
- b - Austausch der Windschutzscheibe
- c - Austausch der Kontrolleinheit / Steuergerät
- d - Austausch, Aus- und Einbau der Kamera
- e - Veränderungen nach einer Fahrwerks-Vermessung
- f - Lenkwinkel Kalibrierung durchgeführt, Höhenstandsensoren ausgetauscht
- g - Schlossträger (VAG) / Frontstoßstange wurde bearbeitet bzw. bewegt